







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



survey report on:

Property address	Tomachlaggan Cottage, Tomintoul, Ballindalloch, AB37 9AR
------------------	---

Customer	Mr T Wilson
----------	-------------

Customer address	

Prepared by Harvey Donaldson And Gibson	Prepared by	Harvey Donaldson And Gibson
---	-------------	-----------------------------

Date of inspection	6th June 2022



Tomachlaggan Cottage, Tomintoul, Ballindalloch, AB37 9AR 6th June 2022

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Х

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

Terms and Conditions

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The property is a detached house.
Accommodation	Ground floor:
	Entrance vestibule, cloakroom W.C., hallway, lounge, kitchen/dining, bedroom 3.
	First Floor:
	Landing, bedroom 1 with en-suite shower room, bedroom 2, bathroom.

Gross internal floor area (m²)	100m2 or thereby	

Neighbourhood and location	The property is in an elevated rural location a few miles from the village of Tomintoul. Larger amenities can be found in Grantown-on-Spey, approximately 14 miles away.
	The property is within the Glenlivet estate and Cairngorms National Park.

Age	Approximately 272 years

ſ		
		, , , , , , , , , , , , , , , , , , , ,
	Weather	The weather was dry and bright during the inspection.

Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	Chimney stacks are stone with mortar flashings.

Roofing including roof space	The roof is pitched and covered with slates.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
Tomoshlaggan Cattaga Tamintaul	Rainwater discharge is via cast iron gutters and uPVC downpipes.

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The walls are of traditional Scottish construction with solid sandstone outer walls, and lath and plaster lined internally. Wall thickness is approximately 600mm.
	The vestibule projection is consistent with being of single block construction.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are uPVC double glazed units. Roof windows are timber double glazed 'Velux' units.
	The external door is timber panelled.
	External joinery is timber.

External decorations	Visually inspected.
	External decorations are painted where applicable.

Conservatories / porches	Visually inspected.
	None.

Communal areas	Circulation areas visually inspected.
	None.

Garages and permanent outbuildings	Visually inspected.	
	None.	

Outside areas and boundaries	Visually inspected.
	There are garden grounds surrounding the house which are mainly grassed. The front is gently sloped and there is a raised stone patio.
	There is a gated private track from the main road. There is a timber decked area and space for parking the to the rear of the property.
	Fences are post & wire.
	There is a timber shed with an asbestos cement roof.
	There are tall mature trees within influencing distance of the property.
	The is a telephone post to the side of the property.
Tomachlaggan Cottage, Tomintoul,	

Ceilings	Visually inspected from floor level.
	The ceilings appear to be lath & plaster and plasterboard.
	Some have a textured plaster finish, e.g. 'Artex'.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are solid masonry, mainly lined with lath & plaster and plasterboard.
	Some have a timber matchboard finish and some have a textured

plaster finish.

Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	The ground floor is partly solid and partly suspended timber, with timber joists and timber floorboards overlaid.
	The upper floor is also suspended timber, with timber joists and timber floorboards overlaid.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal doors are mainly ledged timber panelled units.
	Skirtings and door surrounds are timber.
	The kitchen fittings are traditional in style and consist of floor and wall mounted units. Worktops are timber.

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	The chimney breasts are plastered masonry.
	There is a closed fireplace in the kitchen, which appears to be an older/original feature.
	There is a closed solid fuel stove in the lounge.
	Other fireplaces have been closed off.

Internal decorations	Visually inspected.
	Ceilings, walls and joinery are painted.
Cellars	Visually inspected where there was a safe and purpose-built
	access.
	None.

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains electricity is installed. The meter and consumer unit are located in the kitchen cupboard. The system appears to be of a 13 amp type and design. The switch and socket outlets are plastic and the wiring is sheathed with PVC, where visible.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	None.


Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Water is from a private source which is shared with one other property. This is located nearby: outwith the curtilage.
	Distribution pipes are copper and PVC where visible.
	The bathroom contains a bath with shower over, wash-hand basin and W.C.
	The en-suite contains a shower cubicle, wash-hand basin and W.C.
	The cloakroom contains a wash-hand basin and W.C.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or
	appliances.
	The property is heated by an oil fired system. The boiler is in the kitchen and the hot water cylinder is in the bedroom 3 cupboard. Heating to rooms is by way of water filled radiators.
	The oil fuel storage tank is located at the side of the property.

Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	The property is connected to a private drainage system within the curtilage.
	Under Government legislation the provision of a septic tank within a property requires the consent from SEPA. This agency has powers to ensure the tanks comply with the latest criteria and it is therefore improtant that you ensure the necessary approval.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property has smoke detectors.
	Scottish government regulations have come into effect in February 2022 which require each property to have linked smoke and heat detectors and if gas/carbon burning appliances are present then carbon monoxide alarms are be required. Upgrading may be required to comply with these regulations. Purchasers should satisfy themselves with regard to compliance.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	The weather was dry and bright at the time of the inspection. The property was occupied and furnished. Cupboards held stored items.
	Within the roof space, insulation, stored items and boarding limited the scope of the inspection.
	There was no underfloor hatch.
	It will be appreciated that parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.
	It will be appreciated that parts of the property, which are covered unexposed or inaccessible, cannot be guaranteed to be free from



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movemen	t
Repair category	1
Notes	There is evidence of previous movement in the form of localised hairline cracking to the external building fabric and internally, in the form of off-level floors. The movement is considered to be longstanding in nature with no indication of recent structural deterioration. On the basis of a limited single inspection, no further significant movement is anticipated.

Dampness, rot and infestation	
Repair category	1
Notes	Localised positive moisture meter readings were obtained, e.g. at low level, chimney breast.
	Within the roof space, evidence of wood-boring beetle was noted throughout. Stained timbers were also noted. The owner tells us that timber treatment/preservation works were carried out circa 15 years ago. We assume all documents will be made available where necessary. If no documentary evidence is made available, it would be prudent to instruct a timber & dampness specialist report and to carry out any/all recommended treatments. The costs attached should be fully appreciated.
	There is evidence of pest control measures within the house and roof space. This is typical due to the rural location.

Chimney stacks	
Repair category	1
Notes	Normal weathering was noted, commensurate with age. Evidence of maintenance/repair to the mortar pointing was also noted.

Roofing including roof space	
Repair category	2
Notes	Worn slates were noted. Given the age of the property it would be prudent to check the slating as a matter of course.
	Within the roof space, evidence of wood-boring beetle was noted throughout. Stained timbers were also noted. The owner tells us that timber treatment/preservation works were carried out circa 15 years ago. We assume all documents will be made available where necessary.

Rainwater fittings	
Repair category	1
Notes	Cast iron sections are worn/corroded. Normal and ongoing maintenance will be required.

Main walls	
Repair category	1
Notes	Some localised weathering and spalled stonework were noted.
	Evidence of mortar repairs were noted.

Windows, external doors and joinery	
Repair category	1
Notes	No obvious significant defects were noted to the windows, door or external joinery, allowing for normal wear and tear.

External decorations	
Repair category	1
Notes	No obvious significant defects noted, allowing for normal weathering.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	-
Notes	Not applicable.

Outside areas and boundaries	
Repair category	1
Notes	No obvious significant defects were noted to the outside areas or boundaries. The shed is worn and if removal is planned, specialist advice/contractor will be required.

Ceilings	
Repair category	1
Notes	Minor blemishes and unevenness were noted to the ceilings.

Internal walls	
Repair category	1
Notes	Minor unevenness and blemishes noted, commensurate with age and type.

Floors including sub-floors	
Repair category	1
Notes	Timber floors are off-level in places, especially on the upper floor.

Internal joinery and kitchen fittings	
Repair category	1
Notes	Normal wear noted to the doors and joinery.
	No obvious significant defects were noted to the kitchen fittings, allowing for normal age and wear.

Chimney breasts and fireplaces	
Repair category	1
Notes	No obvious significant defects noted, however there were some positive moisture meter readings at chimney breasts.
	No checks were made to flues or closed fireplaces.
	It is good practice to keep closed off flues permanently ventilated.

☑ Internal decorations	
Repair category	1
Notes	No obvious significant defects, allowing for normal wear and tear. The textured plaster finishes may contain asbestos fibres. This can only be determined by taking a sample for analysis. It is not normally considered to be a health hazard provided it is not disturbed, for example it should not be rubbed down during redecoration.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	2
Notes	It is likely that only the most recently rewired properties will have electrical installations that fully comply with current regulations.
	There is no evidence of a recent test.
	It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.

G as	
Repair category	-
Notes	Not applicable.

Water, plumbing and bathroom fittings	
Repair category	1
Notes	No obvious defects were noted to the water or plumbing fittings where visible. It is prudent to have private water supplies checked annually and to have a regular treatment programme in place. Lenders may require documentation of these before lending. The bath panel is cracked.

Heating and hot water	
Repair category	1
Notes	The system was in use at the time of inspection, and no obvious significant defects were noted, within the limitations of the inspection. It is recommended good practice that oil boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.

Drainage	
Repair category	1
Notes	The drainage pipes are concealed within the building fabric and not available for inspection; however there was no evidence of leakage internally.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	2
Gas	-
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is Outright Ownership.

The property has a private, shared water supply located outwith the curtilage. The drainage is by way of a private septic tank. The legal advisor should check and confirm the details.

The property has a small extension to the front which is older than 20 years. We assume Local authority consents are available where necessary.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

Estimated reinstatement cost for insurance purposes

£341,000 (Three hundred and forty one thousand pounds)

The re-building cost for insurance purposes is for the subject property only and is given solely as a guide.

Valuation and market comments

Market Valuation:

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession on 06 June 2022 is £260,000 (Two hundred and sixty thousand pounds sterling).

Market comment:

There is considered to be a good level of demand for properties of this size and type in the locality.

Signed	Security Print Code [533636 = 7011] Electronically signed

Report author	Donna Shields
---------------	---------------

Company name	Harvey Donaldson And Gibson

Address	Duncan House, Wester Inshes Place, Inverness, Highland, IV2
	5HZ

Date of report	8th June 2022



Tomachlaggan Cottage, Tomintoul, Ballindalloch, AB37 9AR Mr T Wilson 6th June 2022
X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)
ieve that the property was built for the public sector, Yes X No litary, police?
/ Floor(s) on which located No. of floors in block Lift provided?Yes No No. of units in block
Construction 1750
Leasehold Ground rent £ Unexpired years
1 Living room(s) 3 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks)
luding garages and outbuildings) 100 m ² (Internal) 120 m ² (External)
greater than 40%) X Yes No
Dutbuildings
Double garage X Parking space No garage / garage space / parking space X Yes No
JS:

Construction							
Walls	Brick	X Stone	Concrete	Timber frame	Other	(specify in Gen	eral Remarks)
Roof	Tile	X Slate	Asphalt	Felt	Other	(specify in Gen	eral Remarks)
Special Risks							
Has the property suf	fered structur	al movement?				X Yes	No
If Yes, is this recent	or progressive	∋?				Yes	X No
Is there evidence, hi immediate vicinity?	story, or reaso	on to anticipate	e subsidence, l	neave, landslip o	r flood in the	Yes	X No
If Yes to any of the a	above, provide	e details in Ger	neral Remarks.				
Service Connection	on						
Based on visual insp of the supply in Gen			appear to be n	on-mains, please	e comment or	n the type ar	d location
Drainage	Mains X	Private	None	Water	Mains	X Private	None
Electricity	X Mains	Private	None	Gas	Mains	Private	X None
Central Heating	X Yes	Partial	None				
Brief description of C	Central Heatin	g:					
Oil fired central hea	ating. (No gas	in the area).					
Private drainage to	septic tank.						
Private water supp	ly (shared wit	h one other).					
Site							
Apparent legal issue	s to be verifie	d by the conve	eyancer. Pleas	e provide a brief	description ir	n General Re	emarks.
Rights of way	Shared drives	/ access	Garage or other ar	nenities on separate	site X Share	ed service conn	ections
Ill-defined boundaries		Agricultural	land included with	property	Other	(specify in Ger	neral Remarks)
Location							
Residential suburb	Reside	ential within town /	city Mixed	residential / commer	cial 🗌 Mainl	y commercial	
Commuter village	Remot	e village	X Isolate	d rural property	Other	(specify in Ger	neral Remarks)
Planning Issues							
Has the property bee	en extended /	converted / all	tered? X Ye	s No			
If Yes provide details	s in General R	Remarks.					
Roads							
X Made up road	Unmade road	Partly com	pleted new road	Pedestrian a	ccess only	Adopted	Unadopted

General Remarks

The property is in an elevated rural location a few miles from the village of Tomintoul. Larger amenities can be found in Grantown-on-Spey, approximately 14 miles away. The property is within the Glenlivet estate and Cairngorms National Park.

The general condition of the property appears consistent with its age and type of construction. Ongoing maintenance will be required.

Historic settlement was noted in the form of cracking to the external building fabric. No further movement is anticipated.

Small vestibule extension to the front: over 20 years old.

Essential Repairs

None.			
Estimated cost of essential repairs £	Retention recommended?	No	Amount £

Comment on Mortgageability

The property forms suitable security for mortgage purposes, subject to the individual lenders' criteria.

Valuations	
Market value in present condition	£ 260000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 341000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No
Declaration	

Signed	Security Print Code [533636 = 7011] Electronically signed by:-
Surveyor's name	Donna Shields
Professional qualifications	AssocRICS
Company name	Harvey Donaldson And Gibson
Address	Duncan House, Wester Inshes Place, Inverness, Highland, IV2 5HZ
Telephone	01463 718440
Fax	0203 880 9193
Report date	8th June 2022

Energy Performance Certificate (EPC)

Scotland

Dwellings

TOMACHLAGGAN COTTAGE, TOMINTOUL, BALLINDALLOCH, AB37 9AR

Dwelling type:	Detached house
Date of assessment:	06 June 2022
Date of certificate:	08 June 2022
Total floor area:	101 m ²
Primary Energy Indicator:	429 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


0190-2606-5260-2302-2535 RdSAP, existing dwelling Elmhurst Boiler and radiators, oil

You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£4,971	See your recommendations
Over 3 years you could save*	£3,012	report for more information

 * based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band F (35)**. The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band F (30)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Room-in-roof insulation	£1,500 - £2,700	£1830.00
2 Internal or external wall insulation	£4,000 - £14,000	£504.00
3 Floor insulation (suspended floor)	£800 - £1,200	£93.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

TOMACHLAGGAN COTTAGE, TOMINTOUL, BALLINDALLOCH, AB37 9AR08 June 2022 RRN: 0190-2606-5260-2302-2535Rec

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	*****	★★☆☆☆
	Solid brick, as built, no insulation (assumed)	★★☆☆☆	$\star \star \& \& \& \& \& \& \& \& \& \& \& \& \& \& \& \& \& \&$
Roof	Pitched, 100 mm loft insulation Roof room(s), no insulation (assumed)	★★★☆☆ ★☆☆☆☆	★★★☆☆ ★☆☆☆☆
Floor	Solid, no insulation (assumed) Suspended, no insulation (assumed)		_
Windows	Fully double glazed	★★★☆	★★★★☆
Main heating	Boiler and radiators, oil	★★★☆☆	★★★☆☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	★★★☆☆
Secondary heating	None	—	_
Hot water	From main system	★★★ ☆☆	★★★☆☆
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 114 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 12 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 10.5 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy c	osts for this home		
	Current energy costs	Potential energy costs	Potential future savings
Heating	£4,287 over 3 years	£1,485 over 3 years	
Hot water	£444 over 3 years	£234 over 3 years	You could
Lighting	£240 over 3 years	£240 over 3 years	save £3,012
Totals	£4,971	£1,959	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement		
Re	commended measures	indicative cost	per year	Energy	Environment	
1	Room-in-roof insulation	£1,500 - £2,700	£610	D 59	E 51	
2	Internal or external wall insulation	£4,000 - £14,000	£168	D 66	D 59	
3	Floor insulation (suspended floor)	£800 - £1,200	£31	D 68	D 61	
4	Floor insulation (solid floor)	£4,000 - £6,000	£60	C 70	D 64	
5	Upgrade heating controls	£350 - £450	£51	C 72	D 66	
6	Replace boiler with new condensing boiler	£2,200 - £3,000	£43	C 74	D 68	
7	Solar water heating	£4,000 - £6,000	£40	C 76	C 72	
8	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£298	B 86	C 80	
9	Wind turbine	£15,000 - £25,000	£695	A 104	A 97	

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

energ

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Room-in-roof insulation

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

2 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide longlasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

3 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

4 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

5 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

6 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

7 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

8 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

9 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	27,526	(742)	N/A	(2,863)
Water heating (kWh per year)	2,808			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name: Address:	Miss Donna Shields EES/019504 Harvey Donaldson & Gibson Chartered Surveyors Duncan House Wester Inshes Place Highland Inverness IV2 5HZ
Phone number:	01463718440
Email address:	frances.wilson@hdg.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.







PROPERTY QUESTIONNAIRE

Property Address	Tomachlaggan Cottage, Kirkmichael, Ballindalloch, Moray, AB37 9AR
Vendor(s)	Mr Tristan Wilson
Completion Date of Property Questionnaire	01/06/2022 09:51
System Ref:	QT635260





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership							
	How long have you owned the property? 0 Years 3 Months							
2.	Council Tax							
	Which Council Tax band is your property in?							
	A 🖉 B 🕺 C 😣 D 😣 E 😣 F 😣 G 😣 H 😣							
3.	Parking							
	What are the arrangements for parking at your property? Please tick all that apply?							
	Garage 😣 🛛 Allocated parking space 😣 👘 Driveway 🔗							
	Shared parking 🗞 On street 🗞 Resident permit 😣							
	Metered parking 😣 Other (please specify):							
4.	Conservation area							
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?							
5.	Don't know 🔇							
	Is your property a Listed Building, or contained within one (that is a building $Y_{es} \bigotimes$							
	recognised and approved as being of special architectural or historical interest)?							
6.	Alterations/additions/extensions							
	During your time in the property, have you carried out any structural alterations, additions or Yes 🕅							
а.	extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?							
(i)	If you have answered yes, please describe below the changes which you have made:							
(ii)	Did you obtain planning permission, building warrant, completion certificate and other Yes Source on Sents for this work?							
(iv)	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:							



6.	Alterations/additions/extensions	
	Have you had replacement windows, doors, patio doors or double glazing installed in your	Yes 😣
b.	property? If you have answered yes, please answer the three questions below	No 🔗
	Were the replacements the same shape and type as the ones you	Yes 😵
(i)	replaced?	No 😣
	Did the work involve any changes to the window or door openings?	Yes 😣
(ii)		No 😣
	Please describe the changes made to the windows doors, or patio doors (with approximate date completed):	s when the work was
(iii)	Please give any guarantees which you received for this work to your solicitor or estate agent	
7.	Central heating	
	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main	Yes 🧭
a.	rooms of the property —	No 🔇
	the main living room, the bedroom(s), the hall and the bathroom).	Partial 😵
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air)	
	Oil fired If you have answered yes, please answer the three questions below	
(i)	When was your central heating system or partial central heating installed?	2008
	Do you have a maintenance contract for the central heating system?	Yes 😣
(ii)		No 🔗
	If you answered yes please give details of the company with whom you have a maintenance co	ntract
(iii)	When was your maintenance contract last renewed? (Please provide the month and year)	
	Frances Darfamanaa Oartifiaata	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes 🗸
0	lesues that may have affected your property	No 🚫
9.	Issues that may have affected your property Has there been any storm, flood, fire, or other structural damage to your	V 🔊
a.	property while you have owned it?	Yes 😣 No 🐼
	If you have answered yes is the damage the subject of any outstanding	Yes 🔇
	insurance claim?	No 😣
	Are you aware of the existence of asbestos in your property?	Yes 🔇
b.		No 📀
	<u>If you have answered yes</u> please give details:	



10.	Services				
	Please tick which services are connected	ed to your property	and give details of the	supplier	
	Service	Connected	Supplier		
	Gas or liquid petroleum gas	\bigotimes			
	Water mains or private water supply		Private		
a.	Electricity		SSE		
	Mains drainage	\bigotimes			
	Telephone	\otimes			
	Cable TV or satellite		Freeview on Sky	dish	
	Broadband	\otimes			
b.	Is there a septic tank at your property?			Yes 🝼	
D.	If you have answered yes please answ	wer the questions b	below	No 😣	
	Do you have appropriate consents for the	ne discharge of you	ur septic tank?	Yes 📎	
(i)				No 😣	
			Don't know 😣		
	Do you have a maintenance contract fo	r your septic tank?		Yes 😣	
(::)					
(ii)	If you answered yes please give details of the co	have a maintenance contrac	t		
11.	Responsibilities for shared or comm	on areas			
	Are you aware of any responsibility to c			Yes 😣	
	used jointly, such as repair of a shared drive, private road, boundary, or garden area?			No ⊘	
а.				Don't know 🚫	
	If you answered yes please give details				
	Are you aware of any responsibility to c maintenance of the roof, common stairv			Yes 😣	
				No 🝼	
b.				Don't know 🚫	
	If you answered yes please give details				
	No				
C.	Has there been any major repair or repl during the time you have owned the bui		rt of the roof	Yes 😣	
J .		5		No 📀	
	Do you have the right to walk over any of			Yes 😣	
d.	example to put out your bins, or to maintain your boundaries?			No 🔗	
u.	If you answered yes please give details				



PROPERTY QUESTIONNAIRE

11.	Responsibilities for shared or common areas	
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin, or to maintain their boundaries?	Yes 😣
e.	property, for example to put out their rubbish bin, or to maintain their boundaries?	No 🝼
с.	If you answered yes please give details	
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)	Yes 😣
f.		No 📀
	<u>If you answered yes</u> please give details	
12.	Charges associated with your property	
12.	Is there a factor or property manager for your property?	Yes 😣
	is there a lactor of property manager for your property.	No 🐼
a.	If you answered yes please provide name and address and give details relating to deposits held	
	In you answerce yes provide name and dearess and give details relating to deposits new	and enarges
	Is there a common buildings insurance policy?	Yes 😣
		No 🔇
b.		Don't know 😣
	If you answered yes is the cost of insurance included in your monthly/annual factor's charges?	Yes
		No
	Please give details of any other charges you have to pay on a regular basis for the up areas or repair works, for example to a residents' association, or maintenance or stair	
C.	n/a	
13.	Specialist works	
	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes 🗸
	If you answered yes please give further details	No 🚫
a.	Timber treatment/preservation works were carried out circa 15 years ago by pre	vious ownor
а.	Do you have any guarantees for this work?	Yes 🔇
		No 🐼
	Guarantees are held by :	
	As far as you are aware, has any preventative work for dry rot, wet rot, or damp	Yes 🗸
	ever been carried out to your property?	No 😣
	I <mark>f you answered yes</mark> please give further details	
b.	Timber treatment/preservation works were carried out circa 15 years ago by pre-	vious owner.
	Do you have any guarantees for this work?	Yes 😣
		No 🔗
	Guarantees are held by :	



14.	Guarantees					
	Are there any warranties or guarantees for any of the following					
a.		No	Yes	Don't know	With title deeds	Lost
(i) b.	Electrical work		8	\bigotimes	8	8
(ii) b.	Roofing		8	\bigotimes	\bigotimes	8
(iii) b.	Central heating		8	⊗	8	8
(iv) b.	National House Building Council (NHBC)		8	\bigotimes	\bigotimes	8
(v) b.	Damp course		8	⊗	⊗	⊗
(vi)	Any other work or installation? (for example cavity wall insulation, underpinning, indemnity policy)		\bigotimes	\bigotimes	\bigotimes	\bigotimes
b.		1 1				
	Are there any outstanding claims under any of the guarantees listed above?			Yes No 🔗		
с.	If you answered yes please give details					
15.	Boundaries					
	Are you aware has any boundary of your property been moved in the last ten years?			Yes 😣 No 🐼		
a.				Don't know 🔇		
	If you answered yes please give details					



16.	Notices that affect your property	
	In the past three years have you ever receievd a notice :	
a.	Advising that the owner of a neighbouring property has made a planning application?	Yes No 🥑
b.	that affects your property in some other way?	Yes No 🥑
c.	that requires you to perform any maintenance, repairs, or improvements to the property?	Yes No 🥑
	If you answered yes to any of a-c above please give the notices to your so agent, including any notices which arrive at any time before the date of entry of your property	

Declaration by the seller(s) or other authorised body or person(s)

I/We confirm that the information on this form is true and correct to the best of my/our knowledge and belief.

Signatures:

T A Wilson

Date:





Caledonia House Business Centre, High Street, Elgin IV30 1BD 01343 547844 elgin.residential@hdg.co.uk